



# **luxurycarmarket.ae**

Vehicle Inspection Service

[www.luxurycarmarket.ae](http://www.luxurycarmarket.ae)

## Report

- **Reference:** 953
- **Name:** Export safe W
- **Emirate:** Dubai
- **Inspected on:** 2021-11-16

## Vehicle

- **Title:** Ferrari GBT 488
- **Model year:** 2016
- **Manufacturing year:** 2015
- **Chassis number:**  
ZFF79AMT5G0213715
- **Odometer:** 31,858km
- **Condition:** used
- [Open car link](#)

## Additional specs


- **Regional specs:** GCC
- **Exterior color:** Red
- **Interior color:** Red
- **Gearbox:** Automatic
- **Fuel type:** Gasoline
- **Steering side:** Left hand
- **Cylinders:** 8
- **Engine size:** 3.9L
- **Keys:** 2
- **Doors:** 2
- **Seats:** 2

## Warranty / Services


- **Under warranty**
- **Warranty note:** No warranty history found
- **With service history :** As per the seller its full service in agency but need to confirmation

## Inspector summary

1. Front brake percentage 60%, rear brake percentage 59%.
2. Tires percentage 60%, Tires manufacturing date 29 weeks of 2018, Tires Brand Michelin.
















 [Watch Inspection Video](#)

# Vehicle Diagnostic Report

## Vehicle information

Ferrari 458 Italia (F142)

VIN: ZFF79AMT5G0213715

Diagnostics time: 2021/11/16 11:57

Mileage: 31585km

Path: 458 Italia (F142) > Diagnosis > Auto scan >

## Status report

System name	DTC counts	Status
Right Engine (Bosch ME9 master)	0	Pass
Transmission system	0	Pass
Airbag system	0	Pass
TPMS	0	Pass
Parking sensor system	0	Pass
Body Computer Module	0	Pass
Steering assistance	0	Pass
Ion unit	0	Pass
Climate control(Delphi)	0	Pass
Headlamp	0	Pass
Infotainment canbox	0	Pass
Driver door system	0	Pass
Passenger door system	0	Pass
Lifter system	0	Pass
Steering wheel system	0	Pass



# 248 Inspection Points Checked

## Performance

- ✓ Air Suspension
- ✓ Paddle Shifters
- ✓ Hill Start Assist
- ✓ Sport Seats
- ✓ Sport Brakes
- ✓ Sport Suspension
- ✓ Sport Exhaust
- ✓ Launch Control
- ✓ Performance Tires

## Safety

- ✓ Child Safety Seats (ISOFIX)
- ✓ Rear View Camera
- ✓ Front Parking Sensors
- ✓ Rear Parking Sensors
- ✓ Lane Departure Warning
- ✓ Anti-Lock Brakes (ABS)
- ✓ EBD
- ✓ Alarm
- ✓ Front Airbags
- ✓ Side Airbags
- ✓ Traction Control System
- ✓ Anti Glare Rear View Mirror
- ✓ Tire Pressure Monitor

### Interior - Entertainment

- ✔ Digital Driver Display
- ✔ MP3 Player
- ✔ Bluetooth Interface
- ✔ USB

### Interior - Comfort

- ✔ Dual-Zone Climate Control AC
- ✔ Keyless Start
- ✔ Power Steering
- ✔ Cruise Control
- ✔ Power Driver Seats
- ✔ Power Passenger Seats
- ✔ Power Front Windows
- ✔ Power Locks
- ✔ Power Mirrors
- ✔ Power Folding Mirrors
- ✔ Adaptive Lights
- ✔ Leather Seats

### Exterior

- ✔ Front Spoiler
- ✔ LED Headlight

## Inspection Checklist

### Body Exterior

- ✔ Glass
- ✔ Door locks / operation
- ✔ Fuel filler cover / Petrol cap
- ✔ General body condition
- ✔ Corrosion

## Electric Controls

- ✓ Ignition lock / Starting system
- ✓ Battery charging system
- ✓ Headlights
- ✓ Side lights / Running lights
- ✓ Rear lights
- ✓ Indicator / Hazard lights
- ✓ Reverse lights
- ✓ Auxiliary lights
- ✓ Panel lights
- ✓ Horn
- ✓ Window operation
- ✓ Wipers / Jet washers

## Exhaust System

- ✓ Inlet manifold
- ✓ Outlet manifold
- ✓ Pipes
- ✓ Silencer(s)
- ✓ Head shields and mountings
- ✓ Joints and couplings
- ✓ Catalytic converter

## Convenience

- ✓ Keys and remote controls

## Brakes

- ✓ Disc and pads
- ✓ Hand brakes operation

## Road Test

- ✓ Engine - performance
- ✓ Engine - excessive smoke
- ✓ Evidence of overheating
- ✓ Gearbox operation and noise level
- ✓ Instruments and controls functioning
- ✓ Suspension noise
- ✓ Road holding stability
- ✓ Warning lights



## Wheels and Tyres

- ✓ Front right tyre
- ✓ Front left tyre
- ✓ Back right tyre
- ✓ Back left tyre
- ✓ Spare tyre

## Interior and Luggage Compartment

- ✓ Seat belts
- ✓ Internal mirrors
- ✓ Boot / Tailgate lock


## Engine Compartment

- ✓ Coolant level
- ✓ Coolant leaks
- ✓ Radiator cap
- ✓ Hoses and pipes
- ✓ Drive belts
- ✓ Power steering fluid level
- ✓ Engine oil level
- ✓ External engine leaks
- ✓ Engine mounts
- ✓ Turbo / Supercharger
- ✓ Fuel pump and pipes
- ✓ Cold starting
- ✓ Fast idle when engine cold
- ✓ Noise level when engine cold

## Suspension, Underframe and Steering

- ✓ Engine underside leaks
- ✓ Steering joints and ball joints
- ✓ Steering rack
- ✓ Chassis members
- ✓ Power steering
- ✓ Wheels, hubs and bearings
- ✓ Pipes and hoses
- ✓ Dampers and bushes
- ✓ Gaiters
- ✓ Sub frames and mountings
- ✓ Evidence of floor / chassis corrosion

## Damage points



■ Dent ■ RE-Painted ■ Faded ■ Broken ■ Scratch

**Thank you for your business!**

[www.luxurycarmarket.ae](http://www.luxurycarmarket.ae)